

KNIPCO LOW PRESSURE

| MODEL | MOTOR | TRANSFORMER/ IGNITION CONTROL/ IGNITOR | SAFETY/ FLAME-OUT CONTROL | FAN | RELAY | SPARK PLUG/ HSI | INTAKE FILTER | OUTPUT FILTER | NOZZLE | PHOTO CELL | ROTOR KIT ROTOR, BLADES, INSERT | FUEL FILTER | FUEL TANK |
|--------|-----------|--|---------------------------------|-----------|-----------|--------------------|------------------|------------------|-----------|------------|------------------------------------|-------------|-----------|
| F30 | 102762 01 | @102482-01 | HA3003 | M29678 | NLA | HA3013 | M29633 | M29612-01 | M29681 | HA3019 | HA3004 | M50876-01 | NLA |
| F50 | NLA | NLA | HA3003 | NLA | M12462-5 | HA3012 | M11146-1 | | M11054-1 | HA3019 | HA3004 | 079725-01 | NLA |
| F50A | 102762 01 | 102482-01 | HA3003 | M30884 | NLA | HA3013 | M29633 | M29612-01 | M30875 | HA3019 | HA3004 | M50876-01 | NLA |
| F50D | NLA | NLA | HA3003 | NLA | M12462-5 | HA3012 | M11146-1 | NLA | M11054-1 | HA3019 | HA3004 | 079725-01 | NLA |
| F50E | 102001-01 | 102482-01 | HA3003 | M30884 | NLA | HA3013 | M29633 | M29612-01 | HA3007 | HA3019 | HA3004 | M50876-02 | 098513-20 |
| F50S | 102001-14 | 102482-01 | HA3003 | NLA | 107850-01 | HA3012 | M12179 | M12244-1 | M26316 | HA3019 | HA3004 | M19630 | NLA |
| F50F | 102001-01 | 102482-01 | HA3003 | M30884 | NLA | HA3013 | M29633 | M29612-01 | HA3007 | HA3019 | HA3004 | M50876-02 | NLA |
| F50G | 102001-01 | 102482-01 | HA3003 | M30884 | NLA | HA3013 | M29633 | M29612-01 | HA3007 | HA3019 | HA3004 | M50876-02 | 098513-20 |
| F65 | NLA | NLA | HA3003 | NLA | M12462-5 | HA3012 | M11146-1 | NLA | M11054-1 | HA3019 | HA3004 | M19630 | NLA |
| F65D | NLA | NLA | HA3003 | NLA | M12462-5 | HA3012 | M11146-1 | NLA | M26316 | HA3019 | HA3004 | M19630 | NLA |
| F66D | 102001-14 | 102482-01 | HA3003 | M25727 | 107850-01 | HA3012 | M12179 | M12244-1 | M26316 | HA3019 | HA3004 | M19630 | NLA |
| F70 | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA |
| F75 | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA |
| F80 | NLA | NLA | NLA | M14529 | M12462-5 | NLA | NLA | NLA | M18048 | NLA | HA3004 | NLA | NLA |
| F85 | NLA | NLA | NLA | M14529 | M12462-5 | NLA | NLA | NLA | M18048 | NLA | HA3004 | NLA | NLA |
| F85C | NLA | NLA | NLA | M14529 | M12462-5 | NLA | NLA | NLA | M18048 | NLA | HA3004 | NLA | NLA |
| F85E | NLA | NLA | NLA | NLA | NLA | NLA | NLA | NLA | M18048 | NLA | HA3004 | NLA | NLA |
| F88 | NLA | NLA | NLA | M14529 | M12462-5 | NLA | NLA | NLA | M18048 | NLA | HA3004 | NLA | NLA |
| (F98) | NLA | 102482-01 | NLA | M14529 | M12462-5 | HA3012 | M12179 | M12244-1 | M18048 | NLA | HA3004 | NLA | NLA |
| (F98) | NLA | NLA | NLA | M14529 | M12462-5 | NLA | M12179 | M12244-1 | M18048 | NLA | HA3004 | NLA | NLA |
| F98C | NLA | NLA | NLA | NLA | M12462-5 | NLA | M12179 | M12244-1 | M18048 | NLA | HA3004 | NLA | NLA |
| F98D | NLA | 102482-01 | HA3003 | M14529 | M12462-5 | HA3012 | M12179 | M12244-1 | M18048 | HA3019 | HA3004 | M19630 | NLA |
| F110 | NLA | 102482-01 | HA3003 | M23147 | M12462-9 | HA3012 | M12179 | M12244-1 | 100735-05 | HA3019 | NLA | M19630 | NLA |
| F110D | NLA | 102482-01 | HA3003 | M23147 | M12462-9 | HA3012 | M12179 | M12244-1 | 100735-05 | HA3019 | HA3004 | M19630 | NLA |
| F110E | 097300-02 | @102482-01 | 097528-01 | M51153-01 | 097061-01 | HA3012 | M12179 | M12244-1 | #HA3009 | HA3019 | HA3004 | M51150-01 | NLA |
| F110F | 097300-02 | 102482-01 | HA3003 | M51153-01 | 097061-01 | HA3012 | M12179 | M12244-1 | #HA3009 | HA3019 | HA3004 | M51150-01 | 098513-21 |
| F110G | 097300-02 | 102482-01 | HA3003 | M51153-01 | 097061-01 | HA3012 | M12179 | M12244-1 | #HA3009 | HA3019 | HA3004 | M51150-01 | 098513-21 |
| F110H | 097300-02 | 102482-01 | HA3003 | 097293-01 | 097061-01 | HA3012 | M12179 | M12244-1 | #HA3009 | HA3019 | HA3004 | M51150-01 | 098513-21 |
| F120 | 097308-04 | NLA | NLA | NLA | M12462-5 | NLA | M12179 | M12244-1 | NLA | NLA | NLA | NLA | NLA |
| F120D | 097308-04 | NLA | HA3003 | NLA | M12462-5 | NLA | M12179 | M12244-1 | NLA | HA3019 | HA3004 | NLA | NLA |
| FV125C | 097308-04 | 102482-01 | M50230 | NLA | +M12462-6 | HA3012 | M12179 | M12244-1 | 100735-05 | 097059-01 | NLA | NLA | NLA |
| FV125S | 097308-04 | 102482-01 | HA3003 | NLA | +M12462-6 | HA3012 | M12179 | M12244-1 | 100735-05 | HA3019 | NLA | NLA | NLA |
| F140 | 097308-04 | NLA | NLA | NLA | +M12462-6 | NLA | M12179 | M12244-1 | #HA3011 | NLA | NLA | NLA | NLA |
| F140D | 097308-04 | NLA | HA3003 | NLA | +M12462-6 | NLA | M12179 | M12244-1 | #HA3011 | HA3019 | NLA | NLA | NLA |
| F150 | 097308-04 | 102482-01 | HA3003 | M17058 | +M12462-6 | HA3012 | M12179 | M12244-1 | #HA3011 | HA3019 | NLA | M19630 | NLA |
| F150D | 097308-04 | 102482-01 | HA3003 | M17058 | +M12462-6 | HA3012 | M12179 | M12244-1 | #HA3011 | HA3019 | NLA | M19630 | NLA |
| F150E | 097308-04 | 102482-01 | HA3003 | M17058 | 107850-01 | HA3012 | M12179 | M12244-1 | #HA3011 | HA3019 | NLA | M19630 | NLA |
| F150F | 097308-04 | 102482-01 | HA3003 | M17058 | 107850-01 | HA3012 | M12179 | M12244-1 | #HA3011 | HA3019 | HA3004 | M19630 | NLA |
| F150S | 097308-04 | 102482-01 | HA3003 | M17058 | +M12462-6 | HA3012 | M12179 | M12244-1 | #HA3011 | HA3019 | NLA | M19630 | NLA |
| F150G | 097308-04 | 102482-01 | HA3003 | M17058 | 097061-01 | HA3012 | M12179 | M12244-1 | #HA3011 | HA3019 | HA3004 | M19630 | NLA |
| F150H | 097300-02 | 102482-01 | HA3003 | 097293-01 | 097061-01 | HA3012 | M12179 | M12244-1 | #HA3011 | HA3019 | HA3004 | M51150-01 | 098513-55 |
| FV60S | 102001-14 | 102482-01 | HA3003 | NLA | 107850-01 | HA3012 | M12179 | M12244-1 | M26316 | HA3019 | HA3004 | M19630 | NLA |

NLA ----- No Longer Available

* ----- Relay used when capacitor is utilized--Use M12462-17 when not using capacitor - Part #M12650-1 capacitor for 150

@ ----- Bracket number 101206-01 needed for application with transformer